## **GINETEX SWITZERLAND**





WASHING					
normal process	95	normal process	60	mild process	<u>607</u>
normal process	40	mild process	40	very mild process	40
normal process	30	mild process	30	very mild process	30
wash by hand maximum temperature (40°C)		do not wash	×	The numbers in the washing tub sp ximum temperature. *	oecify the ma-
BLEACHING					
any bleaching agent allowed	Δ	only oxygen/non-chlorine bleach allowed		do not bleach	×
DRYING					
tumble drying possible normal temperature (80°C)	<u></u>	tumble drying possible lower temperature (60°C)	0	do not tumble dry	Ø
line drying		drip line drying		flat drying	

## drip flat drying



line drying in the shade



drip line drying in the shade



flat drying in the shade



drip flat drying in the shade



The number of dots indicates the severity as regards to temperature of the tumble drying process. The lines indicate type and position of the natural drying process.

## **IRONING**

Iron at maximum sole plate temperature (200 °C)



Iron at maximum sole plate temperature (150 °C)



The number of dots indicates the severity as regards to temperature of the hand iron.

Iron at maximum sole plate temperature (110 °C) steam may cause damage\*



do not iron



\* steam ironing may cause irreversible damage

## PROFESSIONAL TEXTILE CARE

professional dry cleaning normal process



professional dry cleaning mild process



professional dry cleaning normal process



professional dry cleaning mild process



do not dry clean



The letters within the circle specify the solvents that can be used (P,F) or the wet cleaning process (W). \*

professional wet cleaning normal process



professional wet cleaning mild process



\* General remarks: The bar under the care symbols indicates a mild process (e.g. for easy care articles)

professional wet cleaning very mild process



do not wet clean



The double bar symbolizes a very mild pro